


CERTIFICATE

UPDATED  
CERTIFIED LAND CORNER

No. **56B**  
PAGE 2

I, Harley A. Sime, do hereby certify that on the 7th day of October 1975, I found (evidence) ~~(no evidence)~~ of the Center 1/4 corner of Section 16, T 18 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:



Description of corner evidence found:

Found a 3/4" bolt used in several previous surveys. Said bolt fits the section quite well in a North-South direction, but there is a bad "kink" in bearing in the East-West direction. Accepted the bolt so as to reduce future title problems in regards to survey work done in the past.

UPDATE: A resurfacing project was to take place in the summer of 1993. Prior to construction, the new ties were established and the bolt removed. Following the resurfacing project, a 1 1/4"x12" round iron bar was set at the corner location.

Dated this 10th day of Feb. 19 76.




[Signature]  
County Surveyor  
Title

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

1993 CREW: Bryan Meyer, Rick Lobe  
July, 1993

Witnesses to corner location:

W.C. Jung-Crew Chief [Signature]  
A. Lueck  
D. Malliet



- = Set 1 1/4"x12" round iron bar
- = Existing 3/4" round iron bar
- = Set nail and cap

COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal \_\_\_\_\_  
Vertical \_\_\_\_\_

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City Village or~~ Town La Grange  
County of Monroe

CERTIFICATE

CERTIFIED LAND CORNER

No. 56B

See Pg. 2

I, Harley A. Sime, do hereby certify that on the 7th day of October 1975, I found (evidence) (~~no evidence~~) of the Center 1/4 corner of Section 16, T 18 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

Description of corner evidence found:

Found a 3/4" bolt used in several previous surveys. Said bolt fits the section quite well in a North-South direction, but there is a bad "kink" in bearing in the East-West direction. Accepted the bolt so as to reduce future title problems in regards to survey work done in the past.

Dated this 10th day of Feb. 1976.

Harley A. Sime  
County Surveyor  
Title

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:




Found a 3/4" bolt along the West edge of Hwy. "12" and in the centerline of an E-W Town Road.

Witnesses to corner location:

W.C. Jung-Crew Chief W.C. Jung

A. Ineck

D. Malliet



O = LOCATION CORNER

T 18 N R 1 W

WISCONSIN

COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange

County of Monroe