

CERTIFICATE

CERTIFIED LAND CORNER

No. 77

Pg. 2

21801212000

I, Harley Sime, do hereby certify that on the _____ day of _____ 1974, I found (evidence) (~~no evidence~~) of the W 1/4 corner of Section 22, T18 N, R1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 12 day of March 1975.

Harley Sime
 COUNTY SURVEYOR
 Title

History of original corner establishment:

UPDATED HISTORY:

This corner has been used for several surveys done by many surveyors during the 1970s and 1980s

Description of corner evidence found:

Replaced accepted 1" iron pipe with Harrison monument. This location fit existing conditions and computations well.

UPDATE: DECEMBER, 1990. Found the Harrison marker in good condition. The 6" Pine shown on the previous ties sheet for this corner is now gone (probably destroyed during installation of the underground telephone line). Also the tree shown as a 4" Pine is actually an Oak: Got additional ties as shown below.


Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set standard Harrison monument up 4", just North of a 24" Oak tree with wire running thru the center. Accessories pictured below :

Witnesses to corner location:


SURVEY CREW
K. Pritzlaff - Survey Crew Chief
D. Malliet
B. Jung
A. Lueck

H. A. Sime and Associates
 P. O. Box 705
 Tomah, Wisconsin 54660
 Phone: (608)-372-5392
 SURVEY CONTROL ORDER



NOTE: The 8" Maple, 12" White Pine and 12" Oak are double blazed; the distance to each is to a nail set in a hack in the side of each tree.

WISCONSIN COORDINATE SYSTEM



COUNTY SURVEYOR FORM NO. 1

Horizontal	_____
Vertical	_____

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange
 County of Monroe

CERTIFICATE

CERTIFIED LAND CORNER

No. 77

See Pg. 2

I, Harley Sime, do hereby certify that on the _____ day of _____ 1974, I found (evidence) (~~no evidence~~) of the W 1/4 corner of Section 22, T 18 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

Description of corner evidence found:

Replaced accepted 1" iron pipe with Harrison monument. This location fit existing conditions and computations well.

Dated this 12 day of March 1975.

Harley Sime
COUNTY SURVEYOR
Title


COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:


Set standard Harrison monument up 4", just North of a 24" Oak tree with wire running thru the center. Accessories pictured below :

Witnesses to corner location:

SURVEY CREW
K. Pritzlaff - Survey Crew Chief
D. Malliet
B. Jung
A. Lueck



PLACED
COUNTY SURVEYOR'S
SIGN 6-10-87



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange

County of Monroe