

CERTIFICATE

CERTIFIED LAND CORNER

No. 85

21801220000

I, Harley Sime, do hereby certify that on the _____ day of _____ 1974, I found (evidence) (~~no evidence~~) of the NE corner of Section 27, T18 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

Dated this 13 day of March 1975.

Description of corner evidence found:

Found an existing 2" iron pipe under water at this corner location. It fit previous surveys in the area, and guard stakes were set near it.

Harley Sime
 COUNTY SURVEYOR
 Title



PLACED
 COUNTY SURVEYOR'S
 SIGN 6-10-87

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

The 2" pinched iron pipe was located 18" under water and marked with 2" pipe guard stakes. Accessories shown below

Witnesses to corner location:

SURVEY CREW
K. Pritzlaff - Survey Crew Chief
D. Malliet
B. Jung
A. Lueck



Replaced _____ With _____
 On 9/4/85. Crew: Meyer, Sime
 Comments The 2" pipe shown here is now down 7'± under a dike. I set a 2 1/2" x 7' pipe at the corner. B.M. 1" IRON PIPE IN THE CENTERLINE OF RAILROAD TRACKS

Bearings are Magnetic
 1/ 6/ 75
 WISCONSIN COORDINATE SYSTEM

COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange
 County of Monroe