

96
89

U.S. PUBLIC LAND CORNER MAINTENANCE

Corner ID : E1/4 Sec.29, T18N-R1W
21801292000

DATE	CREW	MONUMENT TYPE -----
June 12, 2015	Zachariah P. Dechant Gary L. Dechant	Existing Railroad spike 1.5' west of traveled center line of Emerson Road (La Grange Ave)

References:

	<u>Bearing</u>	<u>Distance</u>
1) SW corner of House foundation at 11424 Emerson	NE	68.33'
2) Set 3/4"x6' round iron bar	East	38.43'
3) Set 3/4"x24" iron bar 10' northwest of 14"Maple	S57E	43.53'
4) Set 3/4"x24" iron bar 9' north and 5' west of wood fence	N63W	49.62'
5) Existing 3/4" round iron bar, 1' south of SE corner of telephone ped	West	33.00'



CERTIFICATE

I, Harley Sime, do hereby certify that on the _____ day of _____ 19 74 I found (evidence) (~~no evidence~~) of the E 1/4 corner of Section 29, T 18 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 13 day of March 19 75.

Harley Sime
 COUNTY SURVEYOR
 Title

CERTIFIED LAND CORNER

No. 96

History of original corner establishment:

Description of corner evidence found:



Found existing Harrison monument 5" beneath the blacktop, and according to old survey this Harrison replaced an existing iron bar.

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:
 Harrison lies 5" beneath the surface of the road, with accessories listed below :

Witnesses to corner location:

- SURVEY CREW
- K. Pritzlaff - Survey Crew Chief
 - D. Malliet
 - B. Jung
 - A. Lueck



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

PLACED
 COUNTY SURVEYOR'S
 SIGN 5-13-87

City, Village or Town La Grange
 County of Monroe