

125

U.S. PUBLIC LAND CORNER MAINTENANCE

Corner ID : SE Sec.34, T18N-R1W
21801340000


DATE	CREW	MONUMENT TYPE -----
May 1, 2014	Zachariah P.Dechant Gary L. Dechant	Existing 3/4" round iron bar 0.4' east of manhole rim, 1' south of curb, on line with Town Line Road to the west, 14' south Town Line Rd to the east, On line with centerline Forbes Rd north All ties destroyed except iron bar 46.35' NE

References:

	<u>Bearing</u>	<u>Distance</u>
1) Existing 3/4" iron bar, Aluminum cap gone, down 6"	N47E	46.35'
2) Set 3/4"x24' hex iron bar 5' north power pole, down 6"	S63E	40.19'
3) Set 3/4"x24" hex iron bar east of berm, down 8"	S47W	70.10'
4) Set 1/2"x12" iron bar with flange on top, 49' east of SE corner bldg.	N47W	132.39'

COORDINATES:

NOTE: Reference markers 1 & 3 and Harrison set on straight line

Gary L. Dechant

May 1, 2014

I, Bryan H. Meyer, do hereby certify that on the 18th day of November 19 93, I found (evidence) ~~on evidence~~ of the Southeast corner of Section 34, T 18 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 19th day of Nov. 19 93.


Bryan H. Meyer
Deputy County Surveyor
Title

History of corner establishment since Original Government Survey

This corner location was established several years ago and has been used by several surveyors in numerous surveys.

Description of corner evidence found:

A sewer and water project took place in the summer of 1993 destroying the monument of record. I set a 3/4" x 6" iron bar at the corner location using survey data shown on surveys in this area.





Bryan H. Meyer
H. A. Sime and Associates
P. O. Box 705
Tomah, Wisconsin 54660
Phone: (608)-372-5392

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

CREW: Meyer, Lobe
DATE: November 18, 1993
WEATHER: P. Cloudy, Windy 36°±
Witnesses to corner location:

Bryan H. Meyer
Rick Lobe



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City/Village~~ Town of LaGrange/ City of Tomah
County of Monroe

CERTIFICATE

UPDATED
CERTIFIED LAND CORNER

No. 125
Pg. 2

I, Harley A. Sime, do hereby certify that on the 23rd day of March 1976, I found (evidence) ~~(no evidence)~~ of the Southwest corner of Section 35, T 18 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

O.R. Dahl, Co. Surveyor, used this corner in a survey in October of 1868.

Dated this 26th day of March 1976.

Description of corner evidence found:

Found a 3/4"x24" hexagon iron bar used in previous surveys. Removed the iron bar and replaced it with a Harrison marker.

Harley A. Sime
County Surveyor

Title

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:


Set a Harrison marker, down 4", 13 ft. South of the centerline, and 4'± South of edge of the asphalt.

Witnesses to corner location:

W.C. Jung-Crew Chief *W.C. Jung*

D. Malliet

Note: I established the additional ties prior to the paving of Town Line Rd.





Crew: Garold A. Sime, R.L.S.

John Kenworthy

Brian Forsythe

Date: Sept. 9, 1989



COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal
Vertical

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange
County of Monroe

I, Harley A. Sime, do hereby certify that on the 23rd day of March 1976, I found (evidence) (~~no evidence~~) of the Southwest corner of Section 35, T 18 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

O.R. Dahl, Co. Surveyor, used this corner in a survey in October of 1868.

Description of corner evidence found:

Found a 3/4"x24" hexagon iron bar used in previous surveys. Removed the iron bar and replaced it with a Harrison marker.

Dated this 26th day of March 1976.




Harley A. Sime
County Surveyor
Title

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set a Harrison marker, down 4", 13 ft. South of the centerline, and 4'± South of edge of the asphalt.

Witnesses to corner location:

W.C. Jung-Crew Chief W.C. Jung
D. Malliet



COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal _____
Vertical _____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange
County of Monroe