

68

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

**Corner ID : S1/4 Sec. 16, T18N-R2W
21802160020**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
November 4, 2016	Zachariah P.Dechant Gary L. Dechant	Existing Harrison intact at downed fence corner

References:


	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 10"	N48E	20.14'
2) Set 3/4"x24" round iron bar, down 6", 4" south of 12" Black Oak (BT)	S65E	20.25'
3) Set 3/4"x24" round iron bar, down 6", 4' west of 18" White Oak (BT)	S47W	19.17'
4) Set 3/4"x24" round iron bar, down 6", 4' SE 16" White Oak (BT)	N30W	36.72'



CERTIFICATE

I, Nicholas M. Hillmer, do hereby certify that this document and the data contained herein was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Wisconsin.

Dated this 23rd day of May, 2013


 Nicholas M. Hillmer, P.L.S. 2909
 Anderson Engineering of Minnesota, LLC.

CERTIFIED LAND CORNER


History of corner established since Original Government Survey

Fort McCoy surveyors were here in the 1940's. In December of 1987 Gary Dechant found and accepted a fence corner as the best available evidence. Dechant set a Harrison monument and sign.

Description of evidence found

On January 24th, 2013, Anderson Engineering of Minnesota located the Harrison monument 0.3 feet above grade and 0.3 feet south of a witness post with a survey marker sign. Remnants of a fence were found to the west and north. The mark is 1.0 foot east of the apparent fence intersection.

No. 68
21802160020



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Nick Hillmer
Josh Oslund
Dan Greenwald




MONROE COUNTY
 COORDINATE SYSTEM
 NAD 1983 (2007)


HARRISON MONUMENT
 Northing (Y) 410683.22
 Easting (X) 676052.65

Base Station - 22 182W
 Northing (Y) 408053.25
 Easting (X) 679287.00

All distances are shown in U.S. Survey Feet.
 Ties are to 60D nails set in trees.
 Bearings are for tie reference purposes only.
 Coordinates were derived from RTK GNSS procedures.



**See Reverse Side
 For Maintenance**



⊕ = LOCATION CORNER
 Corner I.D. S 1/4 16
T 18 N R 2 W
 Town of Greenfield
 Monroe County, WI.

I, Gary L. Dechant, do hereby certify that on the 22nd day of December 1987, I found (evidence) ~~XXXXXXXX~~ of the N $\frac{1}{4}$ corner of Section 21, T18 N, R 2 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of corner establishment since Original Government Survey

Fort McCoy surveyors were here in the 1940's.

Description of corner evidence found:

Accepted fence corner as best available evidence.


Dated this 31st day of Dec. 1987.

Gary L. Dechant

Registered Land Surveyor, 1744

Title

See Reverse Side For Maintenance





Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

David E. Madison

Gary L. Dechant



Trees double blazed with N&C's set.

SURVEY CONTROL ORDER

Horizontal
Vertical

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~XXXXXXXX~~ Town Greenfield
County of Monroe

COUNTY SURVEYOR FORM NO. 1