

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

No known discrepancies.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?


A found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

Not a lost corner.

(i) I, Ross A. Michaels
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Ross A. Michaels Oct. 22, 1993.



CERTIFICATE

I, Douglas J. Malliet, do hereby certify that on the 19th day of April 19 78, I found ~~(evidence)~~ (no evidence) of the S $\frac{1}{4}$ corner of Section 27, T 19 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 19th day of May 19 78.

Douglas J. Malliet

REGISTERED LAND SURVEYOR, S-1266
Title

CERTIFIED LAND CORNER

No. 106

History of original corner establishment:

No subsequent history of monument perpetuation since the original U.S. Government Survey.

Description of corner evidence found:

This corner was established on line and half-way between the SW and SE corners of Sec. 27. There was no evidence of fences, tree lines or other signs of occupation at this location.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Douglas J. Malliet


Lawrence A. Feddersen

WOODS



nail & washer in blazed 10" Black Oak

set Harrison monument up 2" and surrounded by small stones




nail & washer in blazed 8" Black Oak

nail & washer in blazed 10" Black Oak

nail & washer in blazed 8" Black Oak

WOODS

C/L AUBURN AVENUE



O = LOCATION CORNER

T 19 N R 1 W

WISCONSIN

COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal _____

Vertical _____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town of LINCOLN

County of MONROE