


# CERTIFICATE

I, Nicholas M. Hillmer, do hereby certify that this document and the data contained herein was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Wisconsin.

Dated this 21st day of May, 2013



Nicholas M. Hillmer, P.L.S. 2909  
Anderson Engineering of Minnesota, LLC.

# CERTIFIED LAND CORNER

History of corner established since Original Government Survey

In October of 1901 Holden found a stone at this corner. The 1940's McCoy boundary notes show a corner at this location. In November of 1982 William Jung found and accepted a McCoy boundary monument as the best available evidence of the corner.

Description of evidence found

On November 28th, 2012, Anderson Engineering of Minnesota located the McCoy monument, a 4 inch U.S. Army Corps of Engineers survey control mark disk set in concrete 0.5 feet above grade. The monument is 1.2 feet east of a 4 inch square wood post with a survey marker sign.

No. 21902092000



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Nick Hillmer  
Josh Oslund  
Dan Greenwald


MONROE COUNTY  
COORDINATE SYSTEM  
NAD 1983 (2007)

MCCOY MONUMENT  
Northing (Y) 450005.21  
Easting (X) 678327.95

Base Station - 22 182W  
Northing (Y) 408053.25  
Easting (X) 679287.00



All distances are shown in U.S. Survey Feet.  
Ties are to 60D nails set in trees.  
Bearings are for tie reference purposes only.  
Coordinates were derived from RTK GNSS procedures.



21902092000

I, William C. Jung, do hereby certify that on the 17th day of November 1982, I found (evidence) ~~no evidence~~ of the West 1/4 corner of Section 10, T 19 N, R 2 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 31st day of March 1983.

William C. Jung  
Deputy County Surveyor, R.L.S. 1323  
Title

History of corner establishment since Original Government Survey

When the McCoy boundary was surveyed during World War II, a marker was set at this corner.

Description of corner evidence found:

I found a McCoy boundary marker at the corner. I accepted this monument as the best available evidence of the original government corner.

Approved: **HARLEY A. SIME**  
**MONROE CO. SURVEYOR**


COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

William C. Jung



Dick Abbs



Found a 6" square concrete McCoy marker with a brass cap, up 7", and 3' West of a downed fence. About 1.1' West of the corner is a 4" square post with a survey witness sign on it.

Note:

All bearing trees are double blazed. Each distance is to a nail set in a hack on the side of the tree.



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Grant  
County of Monroe  
Wisconsin