

98

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

Corner ID : E1/4 Sec.27, T19N-R2W
21902272000

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
May 6, 2015	Zachariah P. Dechant Gary L. Dechant	Existing Harrison intact, south side new RR tie post fences running west & south. Set new sign 2' east

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x 24" round iron bar, down 6", 4' south 6" Maple	N69E	20.44'
2) Set 3/4"x24"round iron bar, down 6", 6' south of 13" Double White Oak	S54E	27.00'
3) Set 3/4"x24" round iron bar, down 6", northwest side of 1'x2' flat stone	S25W	29.27'
4) Set 3/4"x24" round iron bar, down 6", 6' SE 10" White Oak	N62W	31.05'

Gary L. Dechant

October 23, 2015

I, Harley A. Sime, do hereby certify that on the 20th day of July 1973, I found (evidence) (~~no evidence~~) of the E 1/4 corner of Section 27, T 19 N, R 2 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 2nd day of March 1978.

History of original corner establishment:

Holden found Kenyon's corner at this point in December of 1906.

Description of corner evidence found:

Accepted occupied fence corner as best available evidence.

County Surveyor Approved: HARLEY A. SIME
Title MONROE CO, SURVEYOR

**See Reverse Side
For Maintenance**




COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set Harrison Monument.

Witnesses to corner location:

L. Fedderson, Crew Chief



O = LOCATION CORNER
T 19 N R 2 W
WISCONSIN

(All trees blazed,
nail and caps set)

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Grant

County of Monroe