

## CERTIFICATE

I, Nicholas M. Hillmer, do hereby certify that this document and the data contained herein was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Wisconsin.

Dated this 21st day of May, 2013



Nicholas M. Hillmer, P.L.S. 2909  
Anderson Engineering of Minnesota, LLC.

## CERTIFIED LAND CORNER

### History of corner established since Original Government Survey

In October of 1901, Fred Holden's notes show an iron bar at this corner. In 1936 David Blencoe found and accepted Holden's corner. Blencoe set an iron pipe. The 1940's McCoy boundary notes show a corner at this location. In September of 1982 William Jung found and accepted Blencoe's pipe as the corner. Jung also found the McCoy monument to the south as a witness corner.

### Description of evidence found

On November 27th, 2012, Anderson Engineering of Minnesota located David Blencoe's 2 1/2 inch pipe with stamped cap 1.4 feet above grade, and the McCoy monument, a 4 inch U.S. Army Corps of Engineers survey control mark disk set in concrete 0.62 feet south of the 2 1/2 inch pipe. The monuments were found in a 3x3x1 foot mound with pits to the east and west.

No. 22002330020



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:



Witnesses to corner location:

Josh Oslund  
Dan Greenwald

MONROE COUNTY  
COORDINATE SYSTEM  
NAD 1983 (2007)

2 1/2 INCH CAPPED PIPE  
Northing (Y) 458309.12  
Easting (X) 675705.73

Base Station - 22 182W  
Northing (Y) 408053.25  
Easting (X) 679287.00



● = LOCATION CORNER  
Corner I.D. N 1/4 4  
T 19 N R 2 W  
Town of Grant  
Monroe County, WI.

All distances are shown in U.S. Survey Feet.  
Ties are to 60D nails set in trees.  
Bearings are for tie reference purposes only.  
Coordinates were derived from RTK GNSS procedures.

22002330020

I, William C. Jung, do hereby certify that on the 28<sup>th</sup> day of September 1982, I found (evidence) ~~no evidence~~ of the North 1/4 corner of Section 4, T 19 N, R 2 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 17<sup>th</sup> day of Dec. 1982.

William C. Jung  
Deputy County Surveyor  
Title

History of corner establishment since Original Government Survey

In October of 1901, Holden's notes show an iron bar at this corner. In about 1936, David Blencoe, from Jackson County, found Holden's buggy axle. He accepted this corner and set an iron pipe. The McCoy boundary notes show that this iron pipe was found and used as the corner.

Description of corner evidence found:




I found Blencoe's pipe at the corner. The McCoy marker 0.48' to the South is a witness corner.

Approved: HARLEY A. SIME  
MONROE CO. SURVEYOR

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

William C. Jung  
Bryan H. Meyer



All B.T.'s double blazed; Each distance to a nail in a hack in the side of the tree.

COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or~~ Town of Grant

County of Monroe