

85


**U.S. PUBLIC LAND CORNER
MAINTENANCE**

**Corner ID : SW Sec.23, T17N-R1E
41701220000**

DATE	CREW	MONUMENT TYPE -----
April 21, 2018	Zachariah P.Dechant Gary L. Dechant	Existing Harrison 18' south of road at remnants of fence corner Survey sign 1' north. All old BT's gone.

References:	Bearing	Distance
1) Set 1"x24" "U" channel iron, down 12" in field	N16E	54.60'
2) Set 1-1/2"x24" iron pipe, down 12" in field	S54E	27.09'
3) Set 1"x24" "U" channel iron, down 6", 4' NE of 8" Shagbark Hickory	S52W	34.15'
4) Set 1-1/2"x24" iron pipe, down 12" in field	N32W	66.27'

Distances measured to closest, middle edge of "U" channel



CERTIFICATE

I, Harley A. Sime, do hereby certify that on the 18th day of March 1980, I found (evidence) (~~no evidence~~) of the SW corner of Section 23, T 17 N, R 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 8th day of April 1980.

Harley A. Sime, R.L.S. 355

County Surveyor

Title

CERTIFIED LAND CORNER

No. 85

History of original corner establishment:
No known history since the original government survey.

Description of corner evidence found:
Accepted the fence corner as best available evidence.

**See Reverse Side
For Maintenance**



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

G. Dechant

C. Pietz

T. Tormoen



(All trees double blazed w/N&C's set)

**Approved: HARLEY A. SIME
MONROE CO. SURVEYOR**

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Oakdale

County of Monroe

COUNTY SURVEYOR FORM NO. 1