

96


**U.S. PUBLIC LAND CORNER
MAINTENANCE**

Corner ID : W1/4 Sec. 28, T17N-R1E

41701292000

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE -----</u>
July 6, 2018	Zachariah P. Dechant Gary L. Dechant	Existing Harrison intact at fence corner. Poured concrete around Harrison. Set survey sign 1' east.

<u>References:</u>	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 6", 5' east of 28" Black Oak (1979 BT)	N25E	13.95'
2) Set 3/4"x24" round iron bar, down 6", 5' NW of 14" White Oak	S60E	14.90'
3) Set 3/4"x24" round iron bar, down 6", 8' NE of 22" White Pine (1979 BT)	S30W	37.37'
4) Set 3/4"x24" round iron bar, down 6", 4' SE of 14" White Pine (1979 BT)	N30'W	16.91'



I, Harley A. Sime 21st, do hereby certify that on the 21st day of December 19 79 I found (evidence) ~~(no evidence)~~ of the West 1/4 corner of Section 28, T 17 N, R 1 E Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of corner establishment since Original Government Survey

No known history recorded since the original government survey.

Description of corner evidence found:

Accepted existing fence corner as best available evidence as it fits field conditions well.

See Reverse Side For Maintenance

Approved: **HARLEY A. SIME**
MONROE CO. SURVEYOR

Title




Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

G. Dechant

B. Meyer

T. Tormoen



NOTE: All trees double blazed with N&Cs set.

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Oakdale
County of Monroe
Wisconsin

COUNTY SURVEYOR FORM NO. 1