

122

**U.S. PUBLIC LAND CORNER
MAINTENANCE**


Corner ID : S1/4 Sec.36, T17N-R1W

21701360020

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
November 8, 2018	Zachariah P. Dechant Gary L. Dechant	Found Harrison intact, at remains of down fence corner. Set sign 1' west

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 4", 5' east of 14" Hickory (1980 BT)	N46E	25.20'
2) Set 3/4"x24" round iron bar, in field, flush, hit solid rock	S27E	21.36'
3) Set 3/4"x24" round iron bar, down 4", 5' SE of 10" Apple	N58W	16.63'
4) Set 3/4"x24" round iron bar, down 4", 4' SE of 18" Double White Oak	N18W	35.18'



I, William C. Jung, do hereby certify that on the 15th day of September 1980, I found (evidence) ~~(no evidence)~~ of the South 1/4 corner of Section 36, T 17 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 29th day of Dec. 19 80.

William C. Jung

William C. Jung R.L.S. 1323
Registered Land Surveyor

Approved: **HARLEY A. SIME**
MONROE CO. SURVEYOR

**See Reverse Side
For Maintenance**

History of corner establishment since Original Government Survey

~~Fred Holden reset this corner in April of 1907.~~

*void
W.C.J. 8/5/82*

Description of corner evidence found:

Accepted an existing fence corner as the best available evidence of the original government corner.


Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:


Jung

Dechant

Meyer



All Trees Double Blazed
With Nail & Cap Set In Each



SURVEY CONTROL ORDER

Horizontal _____
Vertical _____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Tomah
County of Monroe
Wisconsin

COUNTY SURVEYOR FORM NO. 1