

# 38


**U.S. PUBLIC LAND CORNER  
MAINTENANCE**

**Corner ID : E1/4 Sec. 10, T17N-R1W  
21701102000**

DATE	CREW	MONUMENT TYPE -----
September 15, 2018	Zachariah P. Dechant Gary L. Dechant	Found Harrison, top broke off, placed stones around Harrison. South of power line, east of rock ledge. Set sign 1' north.

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4" x 24" round iron bar, down 4" south side of stone	S48E	12.75'
2) Set 3/4"x 24" round iron bar, down 4", 4' north of 8" White Oak	S18W	26.96'
3) Set 3/4"x 24" round iron bar, down 4" toe of slope of rock ledge	S65W	17.23'
4) Set 3/4"x 24" round iron bar, down 4" at toe of slope of rock ledge	N12W	13.95'

*Gary L. Dechant*  
  
*September 15, 2018*

I, Harley A. Sime, do hereby certify that on the 20th day of March 1978, I found (evidence) (~~no evidence~~) of the E 1/4 corner of Section 10, T 17 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 21st day of March 1978.

Harley Sime

County Surveyor  
Title

Approved: **HARLEY A. SIME**  
**MONROE CO. SURVEYOR**

History of original corner establishment:

**Schroeder was here in December of 1894.**

Description of corner evidence found:





**Accepted a 2-way fence as best available evidence.**

**See Reverse Side  
For Maintenance**

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

D. Marten



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Tomah

County of Monroe

COUNTY SURVEYOR FORM NO. 1