95

U.S. PUBLIC LAND CORNER MAINTENANCE

Corner ID : E1/4 Sec. 30, T17N-R1W

21701302000

DATE	CREW	MONUMENT TYPE ----------
September 15, 2018	Zachariah P. Dechant Gary L. Dechant	Found 3/4" round iron re-rod at fence corner. Up 4", sign 1' north. Found 1990 tie – 3/4" iron bar 68.00' east, down 18"

References:	Bearing	Distance
1) Set 3/4" x 24" round iron bar, flush in lawn	S86E	22.94'
2) Set 3/4"x 24" round iron bar, flush in lawn	S27E	20.74'
3) Set 3/4"x 24" round iron bar, down 6", 8' NE of clump of 8" Box Elder	S30W	43.15'
4) Set 3/4"x 24" round iron bar, down 8"	N32W	18.38'

WISCONSIN
GARY L. DECHANT
S-1744
DOUGLAS, WI
LAND SURVEYOR

September 15, 2018

CERTIFICATE

I, Garold A. Sime, do hereby certify that on the 25th day of July 1990, I found (~~evidence~~) (no evidence) of the E¼ corner of Section 30, T 17 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 19th day of October 19 90.

Garold A. Sime

Monroe County Surveyor
Title

CERTIFIED LAND CORNER

No. 95

History of corner establishment since Original Government Survey

No recorded history since the original government survey

Description of corner evidence found:

Set corner on line and equidistant between Section corners

See Reverse Side For Maintenance

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set 3/4" x 48" re-rod in pile of earth

Witnesses to corner location:

Garold A. Sime, R.L.S.

John F. Kenworthy

Brian Forsythe

Bryan Meyer

WISCONSIN GAROLD A. SIME S-1291 TOMAH, WIS. LAND SURVEYOR





T 17 N R 1 W

WISCONSIN

SURVEY CONTROL ORDER

Horizontal	
Vertical	

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village~~ or Town of Tomah

County of Monroe