

# 7

**U.S. PUBLIC LAND CORNER  
MAINTENANCE**

**Corner ID : NW Sec. 3, T16N-R1W  
21701330000**

| DATE              | CREW                                    | MONUMENT TYPE -----   |
|-------------------|---|---|
| November 23, 2018 | Zachariah P. Dechant<br>Gary L. Dechant | Found Harrison, top broke off. Down 8", 2' south & 2' east of fence corner. Sign 2' west. |

| References:   | Bearing | Distance |
|---|---------|----------|
| 1) Set 3/4"x 24" round iron bar, down 10", in field   | N62E    | 22.37'   |
| 2) Set 3/4"x 24" round iron bar, down 4", 6' S. of 40" White Oak (1985 BT)<br>Set 10" round "sparkly" rock over bar | S33E    | 38.33'   |
| 3) Set 3/4"x 24" round iron bar, down 4", 4' north of double 4"-8" Hickory<br>Set flat stone over bar               | S59W    | 41.93'   |
| 4) Set 3/4"x 24" round iron bar, down 8", 1/2' SE of flint rock.  | N34W    | 24.21'   |

*Zachariah P. Dechant*  
  
November 23, 2018

I, Bryan H. Meyer, do hereby certify that on the 19<sup>th</sup> day of June 1985, I found (evidence) ~~no evidence~~ of the Northwest corner of Section 3, T 16 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 3rd day of Feb. 1986.

Bryan H. Meyer  
Deputy County Surveyor  
Title

History of corner establishment since Original Government Survey

W. F. Schroeder, deputy county surveyor, was here in December of 1903. Fred Zietlow was here in February of 1970 and set a 3/4" iron bar. Mr. Zietlow was here again in September of 1970. Duke Marten was here in January 1972.

Description of corner evidence found:

I found Mr. Zietlow's iron bar and replaced it with a Harrison marker.

**See Reverse Side For Maintenance**



COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:



Crew: Meyer, Wilhite  
Date: June 19, 1985 - 4:00 P.M.  
Weather: P. Cloudy, 80°±.

Witnesses to corner location:

Bryan H. Meyer

Dallas Wilhite

NOTE: The three Oak trees shown are not blazed; the distances shown to them are to nails set in the sides of the trees. The Hickory shown is double blazed; the distance shown to it is to a nail set in a hack in the side of the tree.



SURVEY CONTROL ORDER

|            |       |
|------------|-------|
| Horizontal | _____ |
| Vertical   | _____ |

NOTE: The bearings shown are magnetic hand compass bearings.

WISCONSIN COORDINATE SYSTEM

| Corner            | East (X) | North (Y) | Elevation (Z) | Zone |
|-------------------|----------|-----------|---------------|------|
| Control Sta. Name |          |           |               |      |

City ~~Village~~ Town of Wilton  
County of Monroe