

119


**U.S. PUBLIC LAND CORNER
MAINTENANCE**

**Corner ID : W1/4 Sec.36, T17N-R1W
21701352000**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
December 5, 2018	Zachariah P. Dechant Gary L. Dechant	Existing Harrison intact, at fence corner. 1' south of Railroad tie. Set sign 1½' south.

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 3", SW side 2'x2' stone	N30E	12.25'
2) Set 3/4"x24" round iron bar, SE side of stone	S36E	22.55'
3) Set 3/4"x24" round iron bar, 4' NE of 18" Maple (1986 BT)	S40W	18.85'
4) Set 3/4"x24" round iron bar, 5' west of 16" White Oak	N56W	18.92'

Gary L. Dechant

December 7, 2018

CERTIFICATE

CERTIFIED LAND CORNER

No. 119

I, Gary L. Dechant, do hereby certify that on the 20th day of June 19 86, I found (evidence) (~~no evidence~~) of the W¹/₄ corner of Section 36, T 17 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 20th day of June 19 86.

Gary L. Dechant

Registered Land Surveyor-1744
Title

History of corner establishment since Original Government Survey

No known recorded history since the Original Government Survey.

Description of corner evidence found:

Found original B.T. stump, corner falls at old fence corner, fences are now down.

**See Reverse Side
For Maintenance**

COUNTY SURVEYOR FORM NO. 1




Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Happy Birthday to "me"!

Witnesses to corner location:

David E. Madison

Gary L. Dechant



(Trees double blazed with P.K. nails set) WISCONSIN

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Tomah

County of Monroe