

# 79

**U.S. PUBLIC LAND CORNER  
MAINTENANCE**


**Corner ID : E1/4 Sec.23, T17N-R1W**

**21701232000**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
November 12, 2018	Zachariah P.Dechant Gary L. Dechant	Found Harrison intact, between rock ledges. Stones around Harrison. Set sign 1/2' north. Original BT to SW still standing.

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, 1' east of rock ledge	N10E	42.50'
2) Set 3/4"x24" round iron bar, east side rock ledge point	S10E	50.65'
3) Set 3/4"x24" round iron bar, 4' east of west rock ledge	S56W	8.90'
4) Set 3/4"x24" round iron bar, 6' east of west rock ledge	N12W	18.66'



December 20, 2018

I, Harley A. Sime, do hereby certify that on the 1st day of July 1981, I found (evidence) ~~(no evidence)~~ of the E<sup>1</sup>/<sub>4</sub> corner of Section 23, T 17 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 25th day of August 1981.

Harley A. Sime, R.L.S. 355

County Surveyor

Approved: **HARLEY A. SIME**  
**MONROE CO. SURVEYOR**

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

History of corner establishment since Original Government Survey  
 No known recorded history since the original government survey.

Description of corner evidence found:

Found an original bearing tree and set corner at appropriate bearing and distance as per original notes. This point fits the projection of fences very well.

**See Reverse Side For Maintenance**

COUNTY SURVEYOR FORM NO. 1



Witnesses to corner location:

B. Meyer

G. Dechant



(TREES DOUBLE BLAZED WITH NAILS SET)



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or~~ Town Tomah  
 County of Monroe  
Wisconsin