 # 105

U.S. PUBLIC LAND CORNER MAINTENANCE

Corner ID : NE Sec.34, T17N-R1W

21701270000

DATE	CREW	MONUMENT TYPE ----------
November 23, 2018	Zachariah P.Dechant Gary L. Dechant	Found 3/4" round iron bar at fence corner . Fits all three 1981 bearing trees. Falls 2' east of 4" Cedar. Sign 1' south.

References:	Bearing	Distance
1) Set 3/4"x24" round iron bar, down 3", 2' south of 5" Cedar	N6E	11.66'
2) Set 3/4"x24" round iron bar, down 4", 4' west of fence, 4' NE of 16" Hickory (1981 BT)	S5W	15.61'
3) Set 3/4"x24" round iron bar, down 4", 4' south of 18" Hickory (1981 BT)	S70W	20.12'
4) Set 3/4"x24" round iron bar, down 8", 5' west of 10" Hickory	N26W	18.15'

WISCONSIN
GARY L. DECHANT
S-1744
DOUGLAS, WI
LAND SURVEYOR

December 20, 2018

CERTIFICATE

I, Harley A. Sime, do hereby certify that on the 13th day of February 1981, I found (evidence) ~~no evidence~~ of the NE corner of Section 34, T 17 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 16th day of Feb. 1981.

Harley A. Sime, R.L.S. 355

County Surveyor
Title

CERTIFIED LAND CORNER

No. 105

History of corner establishment since Original Government Survey

No known recorded history since the original government survey.

Description of corner evidence found:

Accepted a 4-way fence corner as best available evidence.

See Reverse Side For Maintenance

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

G. Dechant

B. Meyer





Approved: HARLEY A. SIME
MONROE CO. SURVEYOR

(All trees double blazed with N&C's set)

SURVEY CONTROL ORDER

Horizontal	
Vertical	

WISCONSIN COORDINATE SYSTEM

	East (X)	North (Y)	Elevation (Z)	Zone
Corner				
Control Sta. Name				

~~City, Village of~~ Town Tomah

County of Monroe