

99

**U.S. PUBLIC LAND CORNER
MAINTENANCE**


Corner ID : W1/4 Sec. 25, T17N-R1E

41701262000

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
January 26, 2019	Zachariah P. Dechant Gary L. Dechant	Found Harrison Monument intact in east-west fence, facing west. The 1982 shows north-south fence when in fact it has always run east-west. The north arrow on the 1982 tie sheet should be rotated to the right 90°.

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 6", set in deer trail	North	15.29'
2) Set 3/4"x24" round iron bar, down 6", 4' NW of 20" White Oak (1982 BT, blazes plain)	S27E	9.18'
3) Set 3/4"x24" round iron bar, down 6", 6' NE of 6" Red Oak	S44W	28.58'
4) Set 3/4"x24" round iron bar, down 6", 4' SE of 20" double White Oak (1982 BT, blazes plain)	N65W	19.08"



I, Ronald D. Parish, do hereby certify that on the 15th day of December 1982, I found ~~(evidence)~~ (no evidence) of the W $\frac{1}{2}$ corner of Sec. 25, T 17 N, R 1 E Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 24th day of Dec. 1982.

Ronald D. Parish, R.L.S. 1460

Title

History of corner establishment since Original Government Survey
No known history since the original government survey.

Description of corner evidence found:

SET CORNER AT OLD FENCE CORNER WHICH FITS RECORDED DISTANCE & BEARING, REASONABLY WELL.

See Reverse Side For Maintenance



Approved: HARLEY A. SIME
MONROE CO. SURVEYOR

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

RONALD PARISH

DAN DOWNING



SURVEY CONTROL ORDER

Horizontal _____
Vertical _____

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town OAKDALE
County of MONROE

COUNTY SURVEYOR FORM NO. 1