

46


**U.S. PUBLIC LAND CORNER
MAINTENANCE**

**Corner ID : S1/4 Sec.10, T17N-R1W
21701100020**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE -----</u>
November 29, 2018	Zachariah P. Dechant Gary L. Dechant	Existing Harrison intact at remains of fence corner. Sign 1' north. Dug shallow pit S40E, 6.5'.

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 3", 6' SW of twisted 4" Maple	N42E	18.62'
2) Set 3/4"x24" round iron bar, down 3", 4' NW of 14" Maple	S74E	26.65'
3) Set 3/4"x24" round iron bar, down 3", 6' north of 14" White Oak	S5E	29.97'
4) Set 3/4"x24" round iron bar, down 3", 4' SE of 12" White Oak (1978 BT)	N40W	27.34'



I, Harley A. Sime, do hereby certify that on the 20th day of March 1978, I found (evidence) (~~no evidence~~) of the S 1/4 corner of Section 10, T 17 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

Schroeder was here in December of 1894.

See Reverse Side For Maintenance

Description of corner evidence found:

D. Marten accepted a 4-way fence as best available evidence and set a 3/4"x24" iron bar in June of 1972.

Dated this 21st day of March 1978.

Harley Sime

County Surveyor


Title

**Approved: HARLEY A. SIME
MONROE CO. SURVEYOR**



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

G. Dechant



(All trees double blazed and with Nail & cap)



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Tomah

County of Monroe

COUNTY SURVEYOR FORM NO. 1