

# 130


**U.S. PUBLIC LAND CORNER  
MAINTENANCE**

**Corner ID : S1/4 Sec.32, T17N-R1E  
41701320020**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
March 6, 2019	Zachariah P.Dechant Gary L. Dechant	Existing Harrison intact in north- south fence. North of pond, 7' south of Cedar Sapling. Set sign 1' north. Found 1975 ties leaning.

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 24" section of steel fence post (T-post), at toe of slope	N35E	36.00'
2) Set 24" section of steel fence post in pasture	N70E	26.45'
3) Set 24" section of steel fence post in pasture	S52W	20.88'
4) Set 24" section of steel fence post in pasture	N66W	18.16'




I, Garold A. Sime, do hereby certify that on the 14th day of October 1975, I found (evidence) (~~no evidence~~) of the S 1/4 corner of Section 32, T 17 N, R 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

No known history recorded since the original government survey.

Description of corner evidence found:

Set the corner on line between the section corners and in the existing North-South fence.



Dated this 28th day of Feb. 1978.

Garold A. Sime, R.L.S. 1261

Crew Chief, County Surveyor's  
Title Office



**See Reverse Side  
For Maintenance**

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

G. Sime G. A. Sime

A. Lueck



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

Approved by: Harley A. Sime  
County Surveyor

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Oakdale

County of Monroe

COUNTY SURVEYOR FORM NO. 1