

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

32

Corner ID: N1/4 Sec. 7, T18N-R1W


21801060020

DATE	CREW	MONUMENT TYPE
October 16, 2019	Zachariah P. Dechant Gary L. Dechant	Found Harrison intact, 2' north of north edge of ditch. Survey sign 1' south. Steel post on north side. West of ditch intersection, ditches running east-west & SW Harrison down 10".

References:

- 1) Set 3/4"x24" round iron bar, down 10" edge of field
- 2) Set 3/4"x24" round iron bar, down 4", in depression, between ditches
- 3) Set 3/4"x24" round iron bar, down 4", 8' north of 5" Poplar
- 4) Set 3/4"x24" round iron bar, down 10"

Bearing	Distance
N26E	24.44'
South	26.91'
S33W	46.89'
N67W	31.00'



CERTIFICATE

CERTIFIED LAND CORNER

No. 32

I, Harley Sime, do hereby certify that on the _____ day of _____ 19 74, I found ~~(evidence)~~ (no evidence) of the N 1/4 corner of Section 7, T 18 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 25 day of Feb 19 75.

Harley Sime
County Surveyor
Title

History of original corner establishment:

Description of corner evidence found:

Set by best available field evidence (fence intersection). Computations using this method agreed pretty well with recorded measurements.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Standard Harrison monument set up 3". Accessories are as follows :



Witnesses to corner location:

- SURVEY CREW
- K. Pritzlaff - Survey Crew Chief
- D. Malliet
- B. Jung
- A. Lueck

See Reverse Side For Maintenance



6" BOX ELDER (n,c)



O = LOCATION CORNER
T 18 N R 1 W
WISCONSIN

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange
County of Monroe

COUNTY SURVEYOR FORM NO. 1