

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

90
Corner ID: N1/4 Sec. 29, T18N-R1W
21801200020

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u>
October 14, 2019	Zachariah P. Dechant Gary L. Dechant	Found Harrison intact, up 12", 300' south of STH "21". On south side of small island of pine. Sign north side.

References:

- 1) Set 3/4"x24" round iron bar, down 4", 5' SW of 14" White Pine
- 2) Set 3/4"x24" round iron bar, down 4", 4' SW of 10" White Pine
- 3) Set 3/4"x24" round iron bar, down 4", 6' NW of 14" White Pine
- 4) Set 3/4"x24" round iron bar, down 4", 4' SE of 12" White Pine

Bearing Distance

N20E	25.37'
N70E	11.53'
S65E	30.73'
N20W	50.38'



I, Harley Sime, do hereby certify that on the _____ day of _____ 19 74, I found (evidence) (~~no evidence~~) of the N 1/4 corner of Section 29, T 18 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 13 day of March 19 75.

Harley Sime
 COUNTY SURVEYOR
 Title

History of original corner establishment:

Description of corner evidence found:

Replaced 1 1/2" iron pipe with a Harrison monument. The iron pipe was existing 10' + North of existing fence line.


COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:


Set a standard Harrison monument up 2" above ground level, with accessories shown below :

Witnesses to corner location:

- SURVEY CREW
K. Pritzlaff - Survey Crew Chief
D. Malliet
B. Jung
A. Lueck



See Reverse Side For Maintenance



T 18 N R 1 W
 WISCONSIN

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

PLACED
 COUNTY SURVEYOR'S
 SIGN 5-29-87
Replaced 6-12-87

City, Village or Town La Grange

County of Monroe