

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

99

Corner ID: W1/4 Sec. 25, T18N-R1W


21801262000

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u>
October 17, 2019	Zachariah P. Dechant Gary L. Dechant	Found Harrison intact, up 6", Set sign 1' north, in north-south fence, 8' tall aluminum pipe 1/2' east, placed stones around Harrison

References:

- 1) Set 3/4"x24" round iron bar, down 10" in field
- 2) Set 3/4"x24" round iron bar, down 10" in field
- 3) Set 3/4"x24" round iron bar, down 4', 8' west of 30" Black Oak (1975 BT)
- 4) Set 3/4"x24" round iron bar, down 10" in field

<u>Bearing</u>	<u>Distance</u>
N50E	16.08'
S46E	20.66'
S17W	17.35'
N64W	19.42'



I, Harley Sime, do hereby certify that on the _____ day of _____ 1974, I found ~~(evidence)~~ (no evidence) of the W 1/4 corner of Section 25, T 18 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 17 day of March 1975.

Harley Sime
 COUNTY SURVEYOR
 Title

History of original corner establishment:

Description of corner evidence found:


Set this corner by best available field evidence and aerial photos, in a good North-South fence line. Measurements to near corners agree pretty well.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:


Set a standard Harrison monument up 3" in fence line, with accessories as follows:

Witnesses to corner location:

- SURVEY CREW
- K. Pritzlaff - Survey Crew Chief
- D. Malliet
- B. Jung
- A. Lueck



See Reverse Side For Maintenance



O = LOCATION CORNER
 T 18 N R 1 W
 WISCONSIN

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM				
Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange
 County of Monroe

COUNTY SURVEYOR FORM NO. 1