

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

73

Corner ID: NW Sec. 19, T18N-R1W


21802130000

DATE	CREW	MONUMENT TYPE
September 26, 2019	Zachariah P. Dechant Gary L. Dechant	Harrison, top broke off 38' NE of Elk Road, 5' west of center gravel driveway 9998 Elk

References:

- 1) Set 3/4"x24" round iron bar, down 2", 2' SE of sign "The Shed"
- 2) Set 3/4"x24" round iron bar, down 10", edge of field
- 3) Set 3/4"x24" round iron bar, down 2"
- 4) Set 3/4"x24" round iron bar, down 2", 5' SE of south end of lilac
- 5) Existing 3" flat iron, down 6" in center of driveway

Reference markers 1-4 set on straight lines with Harrison



Bearing	Distance
S80E	26.43'
S40E	50.16'
N80W	22.84'
N40W	40.78'
NE	5.51'

I, Harley Sime, do hereby certify that on the _____ day of _____ 19 74, I found ~~(evidence)~~ (no evidence) of the NW corner of Section 19, T 18 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 12 day of March 1975.

Harley Sime
 COUNTY SURVEYOR
 Title

History of original corner establishment:

Description of corner evidence found:

Set Harrison monument by best available field evidence (fences, roads, etc.) which fit computations well.



See Reverse Side For Maintenance

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set standard Harrison monument down 4" beneath the gravel drive of adjacent farmer, with accessories as shown :

Witnesses to corner location:

- SURVEY CREW
- K. Pritzlaff - Survey Crew Chief
 - D. Malliet
 - B. Jung
 - A. Lueck



O = LOCATION CORNER
 T 18 N R 1 W
 WISCONSIN

PLACED COUNTY SURVEYOR'S SIGN 5-19-87

City, Village or Town La Grange

County of Monroe

COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				