

**U.S. PUBLIC LAND CORNER
MAINTENANCE**


54
Corner ID: W1/4 Sec. 18, T18N-R1W
.21802132000

DATE	CREW	MONUMENT TYPE
September 26, 2019	Zachariah P. Dechant Gary L. Dechant	Harrison, down 5" in center of Elgin Ave, 87' west of driveway 21992 Elgin, N&C 1' south & mag nail 1' NW

References:

	Bearing	Distance
1) Set 3/4"x24" round iron bar, down 2", east of shrub, 10' west of 5' hollowed out Willow (BT)	North	27.90'
2) Set 3/4"x24" round iron bar, down 10", edge of field	S36E	46.92'
3) Existing 3/4" round iron bar, down 8"	South	32.77' (33')
4) Set 3/4"x24" round iron bar, down 2", in lawn, in line with SE corner of house	N36W	40.67'

Reference markers set on straight lines with Harrison



I, Harley Sime, do hereby certify that on the _____ day of _____ 1974, I found (evidence) (~~no evidence~~) of the W 1/4 corner of Section 18, T 18 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 27 day of Feb 1975.

Harley Sime
County Surveyor
title

History of original corner establishment:

Description of corner evidence found:

Found existing iron bar in centerline of road, and replaced it with a Harrison monument. distances fit records allowing for minor errors.

**See Reverse Side
For Maintenance**

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set standard Harrison monument down 4" beneath the blacktop.
Accessories described below :

Witnesses to corner location:



SURVEY CREW

K. Pritzlaff - Survey Crew Chief

D. Malliet

B. Jung

A. Lueck



T 18 N R 1 W
WISCONSIN

**PLACED
COUNTY SURVEYOR'S
SIGN 5-13-87**

City, Village or Town La Grange

County of Monroe

COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				