

**U.S. PUBLIC LAND CORNER
MAINTENANCE**


27
Corner ID: SE Sec. 4, T18N-R1W
21801040000

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u>
September 20, 2019	Zachariah P. Dechant Gary L. Dechant	Existing Harrison top broke off, in centerline of Dogwood Ave, 38' east of Division Road, down 4"

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4x24" round iron bar, down 10" in field	N23E	45.92'
2) Set 3/4x24" round iron bar, down 2", 10' west of center of driveway 25021 Dogwood	S24E	41.59'
3) Set 3/4x24" round iron bar, down 10" in field	S23W	46.80'
4) Set 3/4x24" round iron bar, down 6", 15' east of centerline of Division Road	N24W	58.51'

Harrison & reference markers set on straight lines.



I, Harley Sime, do hereby certify that on the 23rd day of October 1974, I found (evidence) (~~no evidence~~) of the S.E. corner of Section 4, T18 N, R1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 25 day of Feb 1975.

Harley Sime
County Surveyor
Title

History of original corner establishment:

Description of corner evidence found:

Found existing iron bar in centerline of town road and replaced it with a Harrison monument.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Standard Harrison monument down 5". Accessories shown below:

Witnesses to corner location:

SURVEY CREW



K. Pritzlaff - Survey Crew Chief

D. Malliet


B. Jung *W.C. Jung*

A. Lueck

COUNTY SURVEYOR FORM NO. 1



See Reverse Side For Maintenance



O = LOCATION CORNER
T 18 N R 1 W
WISCONSIN

PLACED
COUNTY SURVEYOR'S
SIGN 5-13-87

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange
County of Monroe