

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

15 B
Corner ID: C1/4 Sec. 5, T18N-R1W
21801052020

DATE	CREW	MONUMENT TYPE
October 7, 2019	Zachariah P. Dechant Gary L. Dechant	Found 1 1/4" hexagon iron bar down 12" in field 31' north of centerline Desoto Ave.

References:

	Bearing	Distance
1) Set 3/4x24" round iron bar, down 6", 12' north of Desoto Ave centerline	S70E	36.97'
2) Set 3/4x24" round iron bar, down 10", in field	S13E	67.95
3) Set 3/4x24" round iron bar, down 10", in line with north end of shed to the west	South	87.63'
4) Set 3/4x24" round iron bar, down 6", 12' north of Road centerline, 8' east of NE corner of shed south of road	S40W	27.04'



CERTIFICATE

CERTIFIED LAND CORNER

No. 15B

I, Harley A. Sime, do hereby certify that on the 11th day of September 1978, I found ~~(evidence)~~ (no evidence) of the C/4 corner of Section 5, T 18 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 11th day of Jan. 1979.

Harley A. Sime, R.L.S. 355

County Surveyor
Title

History of original corner establishment:

No known recorded history since the original government survey.

Description of corner evidence found:

Set the corner at the intersection of the 1/4 lines.




See Reverse Side For Maintenance

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

G. Dechant-Crew Chief

L. Lakowske



● = LOCATION CORNER
T 18 N R 1 W
WISCONSIN

PLACED COUNTY SURVEYOR'S SIGN 5-19-87

City, Village or Town La Grange

County of Monroe

COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal _____

Vertical _____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				