


**U.S. PUBLIC LAND CORNER
MAINTENANCE**

31
Corner ID: NE Sec. 7, T18N-R1W
21801060000

DATE	CREW	MONUMENT TYPE
October 16, 2019	Zachariah P. Dechant Gary L. Dechant	Found Harrison intact at fence corner sign 1' SW

References:

	Bearing	Distance
1) Set 3/4"x24" round iron bar, down 10" in field	N21E	23.17'
2) Set 3/4"x24" round iron bar, down 4", in marsh grass, 4' east of fence	S30E	12.00'
3) Set 3/4"x24" round iron bar, down 4", 9' NE of 22" White Pine in pasture	S38W	42.58'
4) Set 3/4"x24" round iron bar, down 10" in field	N33W	23.05'



I, Harley Sime, do hereby certify that on the _____ day of _____ 19 74, I found ~~(evidence)~~ (no evidence) of the NW corner of Section 7, T 18 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 25 day of Feb 1975.

Harley Sime
County Surveyor
Title

History of original corner establishment:

Description of corner evidence found:

Corner was set by best available field evidence, and agreement of property owners.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Standard Harrison monument up 3". Accessories shown below :

Witnesses to corner location:

SURVEY CREW



K. Pritzlaff - Survey Crew Chief

D. Malliet

B. Jung

A. Lueck

See Reverse Side For Maintenance



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange
County of Monroe

COUNTY SURVEYOR FORM NO. 1