

CERTIFICATE

I, Nicholas M. Hillmer, do hereby certify that this document and the data contained herein was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Wisconsin.

Dated this 23rd day of May, 2013



Nicholas M. Hillmer, P.L.S. 2909
Anderson Engineering of Minnesota, LLC.

CERTIFIED LAND CORNER

History of corner established since Original Government Survey

Fred A. Holden set an iron pipe at the corner from the original bearing trees. In 1985 Gary L. Dechant found a 3/4 inch by 34 inch iron bar inside of Holden's pipe. Dechant replaced the pipe with a Harrison monument.

Description of evidence found

On February 25th, 2013, Anderson Engineering of Minnesota located the Harrison monument 9 inches below the road surface and 2.5 feet west of the centerline of the road.

No. 21902322000

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:



Nick Hillmer
Josh Oslund
Dan Greenwald

MONROE COUNTY
COORDINATE SYSTEM
NAD 1983 (2007)

HARRISON MONUMENT
Northing (Y) 428892.92
Easting (X) 673218.63

Base Station - 22 182W
Northing (Y) 408053.25
Easting (X) 679287.00

All distances are shown in U.S. Survey Feet.
Bearings are for tie reference purposes only.
Coordinates were derived from RTK GNSS procedures.



⊙ = LOCATION CORNER
Corner I.D. E 1/4 32
T 19 N R 2 W
Town of Grant
Monroe County, WI.

21902322000

I, Gary L. Dechant, do hereby certify that on the 21st day of November 1985, I found (evidence) of the W 1/4 corner of Section 33, T 19 N, R 2 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 25th day of Nov. 1985.

Gary L. Dechant Registered Land Surveyor-1744 Title

History of corner establishment since Original Government Survey

Fred Holden set an iron pipe at the corner from the original bearing trees.

Description of corner evidence found:


Found a 3/4"x34" iron bar inside of Holden's iron pipe. Holden's iron pipe and the upper 2/3 of the iron bar were bent over and lying flat. Replaced with a Harrison Monument.

Gary L. Dechant WISCONSIN LAND SURVEYOR GARY L. DECHANT S-1744 CAMP DOUGLAS, WI Nov. 25, 1985

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:



Slight snow cover 2:45 P.M. 15°



Witnesses to corner location:

Lawrence A. Feddersen S-1226

Gary L. Dechant



(Trees double blazed, scribed, P.K. nails set)

SURVEY CONTROL ORDER

Table with 2 columns: Control type (Horizontal, Vertical) and status (checkboxes)

WISCONSIN COORDINATE SYSTEM

Table with 5 columns: Corner, East (X), North (Y), Elevation (Z), Zone

City, Village or Town Grant County of Monroe