

**U.S. PUBLIC LAND CORNER  
MAINTENANCE**

# 112


Corner ID: N1/4 Sec. 31, T18N-R1W

21801300020

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u>
October 16, 2019	Zachariah P. Dechant Gary L. Dechant	Found Harrison, top broke off, large stone on east side, sign 1' north.

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 4", 8' SW of marsh/swamp	N30E	24.40'
2) Set 3/4"x24" round iron bar, down 4", 4' SW of 7" White Oak	N78E	11.59'
3) Set 3/4"x24" round iron bar, down 10", edge of field	S9W	14.87'
4) Set 3/4"x24" round iron bar, down 4", 4' NE of double 5" Catulpa	S57W	9.56'



December 23, 2019

I, Harley Sime, do hereby certify that on the \_\_\_\_\_ day of \_\_\_\_\_ 1974, I found (evidence) (~~no evidence~~) of the N 1/4 corner of Section 31, T 18 N, R 1 W., Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

Description of corner evidence found:

Found an existing iron pipe previously used as Section corner and replaced it with a Harrison monument.

Dated this 17 day of March 1975.

Harley Sime  
COUNTY SURVEYOR  
Title

**See Reverse Side  
For Maintenance**

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set a standard Harrison monument up 3", with accessories as shown below :

Witnesses to corner location:



SURVEY CREW

K. Pritzlaff - Survey Crew Chief

D. Malliet

B. Jung

A. Lueck



O = LOCATION CORNER

T 18 N R 1 W

WISCONSIN

**PLACED  
COUNTY SURVEYOR'S  
SIGN 5-26-87**

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange

County of Monroe

COUNTY SURVEYOR FORM NO. 1