

**U.S. PUBLIC LAND CORNER
MAINTENANCE**


78

Corner ID: W1/4 Sec. 23, T17N-R1E
41701222000

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT INFO</u>
April 22, 2020	Zachariah P. Dechant Gary L. Dechant	Existing Harrison intact. Place concrete and stones around monument. Set sign 2' north. Falls 35' east & 57' north of fence corner.

	<u>Compass Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" iron pipe, down 4", 4' south of 10" Maple	N7E	31.60'
2) Set 3/4"x24" iron pipe, down 4", 4' NW of 12" White Oak	S70E	34.27'
3) Set 3/4"x24" iron pipe, down 6", 4' NE of 8" White Oak	S46W	35.57'
4) Set 1/2"x24" iron pipe, down 6", 4' east of 7" Black Oak w/ nail & cap (1980 BT)	S87W	15.93'

Not much growth which is very unusual for a Black Oak



I, Harley A. Sime, do hereby certify that on the 19th day of March 1980, I found ~~evidence~~ (no evidence) of the W. 1/4 corner of Sec. 23, T 17 N, R 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 8th day of April 1980.

Harley A. Sime R.L.S. 355

County Surveyor

History of original corner establishment:
No known history since the original government survey.

Description of corner evidence found:
Set on line and equidistant between section corners.


See Reverse Side For Maintenance

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

G. Dechant

T. Tormoen



All trees double blazed w/ N.&C.'s

Approved: HARLEY A. SIME
MONROE CO. SURVEYOR

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Oakdale

County of Monroe

COUNTY SURVEYOR FORM NO. 1