


**U.S. PUBLIC LAND CORNER
MAINTENANCE**

79

**Corner ID: E1/4 Sec. 23, T17N-R1E
41701232000**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT INFO</u>
April 25, 2020	Zachariah P. Dechant Gary L. Dechant	Existing Harrison. Placed concrete around monument and set sign 1/2' north. Falls on steep slope

	<u>Compass Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 6"	S76E	18.54'
2) Set 3/4"x24" round iron bar, down 6"	S40W	6.77'
3) Set 3/4"x24" round iron bar, down 6", east side of large stone	S78W	66.85'
4) Set 3/4"x24" round iron bar, down 6"	S89W	18.79'



I, Harley A. Sime, do hereby certify that on the 18th day of March 1980, I found ~~(evidence)~~ (no evidence) of the E. 1/4 corner of Sec. 23, T. 17 N, R. 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 8th day of April 1980.

Harley A. Sime R.L.S. 355

County Surveyor

History of original corner establishment:

No known history since the original government survey.

Description of corner evidence found:

Set on line and equidistant between section corners.

See Reverse Side For Maintenance

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:



Witnesses to corner location:

G. Dechant

C. Pietz

T. Tormoen

All trees double blazed w/N.&C.'s set.



Approved: **HARLEY A. SIME**
MONROE CO. SURVEYOR

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Oakdale
County of Monroe

COUNTY SURVEYOR FORM NO. 1