

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

78 B

**Corner ID: C1/4 Sec. 23, T17N-R1E
41701232020**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT INFO</u>
April 25, 2020	Zachariah P. Dechant Gary L. Dechant	Existing 1 1/4" round iron bar. Large flat stone and steel post on east side

	<u>Compass Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 10" in field	N69E	31.41'
2) Set 3/4"x24" round iron bar, down 10" in filed	S13W	26.65'
3) Set 3/4"x24" round iron bar, down 6", 4' east of SE corner of deer stand	West	18.23'
4) Set 3/4"x24" round iron bar, down 6", 5' SE of 30" White Oak (1980 BT)	N50W	25.74'

Gary L. Dechant
WISCONSIN
GARY L.
DECHANT
S-1744
DOUGLAS, WI
LAND SURVEYOR
April 27, 2020

I, Harley A. Sime, do hereby certify that on the 17th day of March 1980, I found (evidence) ~~(no evidence)~~ of the C¹/₄ corner of Section 23, T 17 N, R 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 8th day of April 1980.

Harley A. Sime, R.L.S. 355

County Surveyor
Title

History of original corner establishment:
No known history since the original government survey.

Description of corner evidence found:
Set by the intersection of the N-S, E-W quarter lines.
Fits Downed fences very well.

**See Reverse Side
For Maintenance**


Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:


G. Dechant

C. Dade

T. Tormoen



(All trees double blazed with N&C's set)



**Approved: HARLEY A. SIME
MONROE CO. SURVEYOR**

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Oakdale
County of Monroe

COUNTY SURVEYOR FORM NO. 1