

U.S. PUBLIC LAND CORNER
MAINTENANCE


75

Corner ID: E1/4 Sec.19, T17N-R4W

21704192000

DATE	CREW	MONUMENT INFO
May 14, 2020	Zachariah P. Dechant Gary L. Dechant	Existing Harrison intact, on east bank of gully, set new sign 1' north

	Compass Bearing	Distance
1) Set 3/4"x24" round iron bar, 4' SW of 9" Hickory	N38E	37.26'
2) Set 3/4"x24" round iron bar, 4' NW of 10" Hickory	S88E	45.68'
3) Set 3/4"x24" round iron bar, down 6", south & west of gully on flat ground	S46W	46.08'
4) Set 3/4"x24" round iron bar, north & west of gully, near SE corner of field	N50W	67.43'
5) Existing-sump pump base (1975 tie)	SE	17.75'



CERTIFICATE

I, Harley A. Sime, do hereby certify that on the 10 day of July 1975, I found ~~(evidence)~~ (no evidence) of the E 1/4 corner of Section 19, T17 N, R 4W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 29 day of Jan. 1976.

Harley A. Sime
County Surveyor
Title

CERTIFIED LAND CORNER

History of original corner establishment:

Description of corner evidence found:

Set the corner proportionately between the section corners.

No. 75
See New Sheet

See Reverse Side For Maintenance






Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set a Harrison marker, up 6", 1 ft. East of edge of top of bank. All trees were blazed

Witnesses to corner location:

W.C. Jung - Crew Chief *W.C. Jung*
D. Dade
G. Dechant



COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal _____
Vertical _____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Sparta

County of Monroe

CERTIFICATE

UPDATED
CERTIFIED LAND CORNER

No. 75

PAGE 2

I, Harley A. Sime, do hereby certify that on the 10 day of July, 1975, I found ~~(evidence)~~ (no evidence) of the E 1/4 corner of Section 19, T17 N, R 4W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

O. R. Dahl was at this corner in May of 1868. This corner has been used by numerous surveyors in their surveys in Sections 19 & 20.

Description of corner evidence found:

Set the corner proportionately between the section corners.



See Reverse Side For Maintenance

Dated this 22 day of Jan., 1976.

Harley A. Sime
County Surveyor
Title




Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set a Harrison marker, up 6", 1 ft. East of edge of top of bank.

All trees were blazed and the 5" Hickory & the 10 W. Oak have a nail set in a hack in the side of the tree.

Witnesses to corner location:


W.C. Jung - Crew Chief *W.C. Jung*
D. Dade
G. Dechant



T 17 N R 4W

WISCONSIN

Crew: Garold A. Sime, R.L.S. (Monroe Co. Surveyor)
John Kenworthy
Brent Kostka



SURVEY CONTROL ORDER

Horizontal		WISCONSIN COORDINATE SYSTEM		
Vertical	East (X)	North (Y)	Elevation (Z)	Zone
Corner				
Control Sta. Name				

City, Village or Town Sparta
County of Monroe

COUNTY SURVEYOR FORM NO. 1