

**U.S. PUBLIC LAND CORNER
MAINTENANCE**


28

Corner ID: S1/4 Sec.4, T18N-R1W
21801040020

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT INFO</u>
May 20, 2020	Zachariah P. Dechant Gary L. Dechant	Existing mag nail 12' west of center of USH "12" & 9' south of center of dogwood Ave. Found 1 1/4" round iron bar destroyed just to the south of mag nail. Mag nail is the corner

	<u>Compass Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, 4' SW of 22" Maple in lawn	N56E	86.66'
2) Set 3/4"x24" round iron bar, down 10" in field	S70E	79.80'
3) Set 3/4"x24" round iron bar, down 10" in field	S56W	52.05'
4) Set 3/4"x24" round iron bar, down 10" in field	N70W	50.32'
5) Existing 3/4" round iron bar and sign 1' west	West	30.21

Corner and reference markers 1-4 set on straight lines



I, Harley Sime, do hereby certify that on the _____ day of _____ 19 74, I found (evidence) (no evidence) of the S 1/4 corner of Section 4, T18 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

**See Reverse Side
For Maintenance**

Description of corner evidence found:

This corner was set midway between opposite Section corners and on same line. Fit existing Stae Highway plans well.

UPDATE: A resurfacing project was to take place in the summer of 1993. Prior to construction, the distances to previous ties were checked and new ties taken. The Harrison was then removed. Following the resurfacing project, a 1 1/4" x 30" round iron bar was set at the corner location.



Dated this 25 day of Feb 1975

Harley Sime
County Surveyor
Title

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

SURVEY CREW
K. Pritzlaff - Survey Crew Chief
D. Malliet
B. Jung W.L. Jung
A. Lueck



SURVEY CONTROL ORDER

Horizontal _____
Vertical _____

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange
County of Monroe

COUNTY SURVEYOR FORM NO. 1

I, Harley Sime, do hereby certify that on the _____ day of _____ 19 74, I found (evidence) (no evidence) of the S 1/4 corner of Section 4, T 18 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 25 day of Feb 1975.

Harley Sime
County Surveyor
Title

History of original corner establishment:

**See Reverse Side
For Maintenance**

Description of corner evidence found:

This corner was set midway between opposite Section corners and on same line. Fit existing Stae Highway plans well.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Standard Harrison monument 4" below gravel, just off the pavement.
Accessories shown below :

Witnesses to corner location:




SURVEY CREW

K. Pritzlaff - Survey Crew Chief

D. Malliet

B. Jung *W.C. Jung*

A. Lueck



T 18 N R 1 W
WISCONSIN

SURVEY CONTROL ORDER

Horizontal _____
Vertical _____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange
County of Monroe

COUNTY SURVEYOR FORM NO. 1