

**U.S. PUBLIC LAND CORNER
MAINTENANCE**


16 B

**Corner ID: C1/4 Sec.4, T18N-R1W
21801042020**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT INFO</u>
May 20, 2020	Zachariah P. Dechant Gary L. Dechant	Existing mag nail in center CTH "O", 23' north of center of driveway 7428

	<u>Compass Bearing</u>	<u>Distance</u>
1) Existing 3/4" round iron bar as per CSM's	East	33.00'
2) Set 3/4"x24" round iron bar, center of driveway 7428 CTH "O"	S68E	59.73'
3) Set 3/4"x24" round iron bar in wet lowland	West	50.25'
4) Set 3/4"x3' round iron bar, in lowland	N68W	55.96'

Corner and reference markers set on straight lines



I, Harley A. Sime, do hereby certify that on the 11th day of July 19 74, I found ~~(evidence)~~ (no evidence) of the Center 1/4 corner of Section 4, T 18 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 18th day of Feb. 19 76.

Harley A. Sime
 County Surveyor
 Title

History of original corner establishment:

Description of corner evidence found:

Set the corner "by law" after surveying out Section 4.

See Reverse Side For Maintenance




Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

**Set a 1 1/4" iron bar, down 8", just off the West edge of the pavement.
 The iron bar is also about 5'± North of the fence.**

Witnesses to corner location:

K. Pritzlaff - Crew Chief

W.C. Jung W.C. Jung



(The trees were blazed and n&c's were set in them.)

SURVEY CONTROL ORDER

Horizontal _____
 Vertical _____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange

County of Monroe

COUNTY SURVEYOR FORM NO. 1