U.S. PUBLIC LAND CORNER MAINTENANCE

 # 84

Corner ID: S1/4 Sec.23, T18N-R1W

21801230020

DATE	CREW	MONUMENT INFO
August 17, 2020	Zachariah P. Dechant Gary L. Dechant	Found Harrison, top broke off, Existing 2" iron pipe up 18" with rain gage east side of Harrison

	Compass Bearing	Distance
1) Set 2' section of steel T post, down 6", center of north-south dike	N5E	59.65'
2) Set 2' section of T' post, down 6", 10' north of center of east-west dike	N76E	77.42'
3) Set 2' section of T post, down 6", 15' south of ditch running west	S54W	37.16'
4) Set 2' section of T post, down 6", 12' north of east- west dike	N32W	34.56'

WISCONSIN
GARY L. DECHANT
S-1744
CAMP DOUGLAS, WI
LAND SURVEYOR

CERTIFICATE

I, Harley Sime, do hereby certify that on the _____ day of _____ 19 74, I found ~~(evidence)~~ (no evidence) of the N 1/4 corner of Section 26, T 18 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 13 day of March 19 75.

Harley A. Sime

COUNTY SURVEYOR
Title

CERTIFIED LAND CORNER

No. 84

History of original corner establishment:

See Reverse Side For Maintenance

Description of corner evidence found:

Set corner midway and on line between opposite Section corners.

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set a standard Harrison monument flush with the ground, with an oak post set just NW of marker - up 3'
Other accessories as shown below :

Witnesses to corner location:

SURVEY CREW

K. Pritzlaff - Survey Crew Chief

D. Malliet

B. Jung

A. Lueck



PLACED
COUNTY SURVEYOR'S
Sign 6-10-87



O = LOCATION CORNER

T 18 N R 1 W

WISCONSIN

SURVEY CONTROL ORDER

Horizontal	
Vertical	

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange

County of Monroe